

Homeowner Test Results Guidance

Strategy using short-term initial test

Step 1

Initial Short-Term Test

Is the result equal to or greater than 4 pCi/l?

No
No Mitigation recommended*

Yes

Yes

If result is equal to or greater than 8 pCi/l

If result is less than 8 pCi/l, Choose follow-up test type

Perform confirming Short-Term Test

Perform Long-Term Test (Full year recommended)

Step 2

No Mitigation, but a Year-Long Test is recommended

No

Is the Average of 1st and 2nd test at or above 4 pCi/l?

Yes

Mitigate Home

Yes

Is the Result of LONG-TERM test at or above 4 pCi/l?

No

No Mitigation recommended

*Note: If you tested in the summer, if the result is less than 4.0 pCi/l, we recommend a follow-up test during the heating season, or a year-long test.